9-16-26

E OR L	Trailer #	LOCK	Comments
E	44413	Y	check bearings, ABS, cable.
E	6428	Y	left rail was hit, side rail cracked,
E	96884	Y	TRL was hit in rail, damage to rail & wall.
E	8935	Y	wall pushed out both sides,
E	44410	Y	brakes, drums, wheel bearings,
E	8939	Y	needs to be plated behind rail,
E	8951	Y	~~rail~~ side wall pushed out rejected at PCA TN.
E	8949	Y	ABS light.
E	6431	Y	nail in LRD tire,
E	244	Y	reefer ok
E	30672	Y	reefer ok
E	989701	Y	scp ok
E	6451	Y	Annual
L	2944	n	Ready
L	8927	n	Ready
L	2881	n	behind TR 296 got new tires all away around.
L	968887	n	Ready
L	8928	n	Ready
L	8961	n	Ready
L	6434	n	Ready
L	3183	n	Ready
E	5323758	Y	go over check out
E	8933	Y	check out

T235-EX225L266XX001