9-25-24

	E OR L	TRAILER #	LOCK	COMMENTS
	E	44413	Y	check wheel bearings
	E	6428	Y	left rail was hit side wall creaked,
	E	968884	Y	tail was hit in rail damaged rail & wall.
	E	8935	Y	wall pushed out both sides
	E	44410	Y	brakes, drums, wheel bearings.
	E	8939	Y	needs plated behind rail.
	E	8951	Y	side wall pushed out, rejected at PCA yn.
	E	968876	Y	scuffboard.
	E	968879	Y	scuffboard.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scp ok.
1	L	968865	n	right side dolly leg needs new one.
*	L	6422	Y	Annual.
	L	6441	n	Ready
	L	968871	n	Ready
	L	968867	n	Ready
	L	3180	n	Ready
*	L	2886	Y	Annual.
*	L	2956	Y	needs mud flap fixed
	E	2940	n	Ready
	E	2951	n	Ready
	E	968870	n	Ready
	E	6429	n	Ready
	E	3175	n	Ready
	E	6451	n	Ready
	E	2870	n	Ready