9-26-26

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	check wheel bearings
E	6428	Y	left rail was hit side wall creched,
E	968884	Y	tnl was hit in rail damaged rail & wall.
E	8935	Y	wall pushed out both sides,
E	44410	Y	brakes, drums, wheel bearings
E	8939	Y	needs plated behind rail
E	8951	Y	side wall pushed out, rejected PCA+TN.
E	968876	Y	scuffboard.
E	968879	Y	scuffboard.
E	244	Y	reefer ok
E	30672	Y	reefer ok.
E	989701	Y	sep ok.
L	8952	n	Ready
L	8962	n	Ready
L	968877	n	Ready
L	968878	n	Ready
* L	2871	Y	Annual
L	2878	n	Ready
* E	968871	Y	Annual
L	968867	n	Ready
L	3180	n	Ready
L	8941	n	Ready
L	2954	n	Ready
* L	8594	Y	Annual
L	2486	n	Ready
L	6422	n	Ready
E	2940	n	Ready
* E	44380	Y	Flat on RRI
E	968870	n	Ready
E	5624269	n	Ready
E	3175	n	Ready

* E 44525 Y need spring
E 2870 Ready
E 6451 Ready