9-29-26

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	check wheel bearings
E	6428	Y	left rail was hit side wall creched.
E	968884	Y	til was hit in rail damaged + wall.
E	8935	Y	wall pushed out both sides
E	44410	Y	brakes, drums, wheel bearings
E	8939	Y	needs plated behind rail.
E	8951	Y	side wall pushed out, rejected PCA, TN.
E	968879	Y	scuffboard.
E	968879	Y	scuffboard.
E	244	Y	reefer ok
E	30672	Y	reefer ok.
E	989701	Y	scp ok.
E	8965	n	Ready
L	968867	n	Ready
L	44286		behind TL 421
L	6422	n	Ready
L	2886	n	Ready
L	44635	n	Ready
E	44380	n	Ready
E	44525	n	Ready
E	6451	n	Ready