10-3-2024

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	Check wheel bearings
E	44410	Y	brakes, drums, wheel bearings
E	8935	Y	wall pushed out
E	8939	Y	needs plated behind rail
E	8951	Y	side wall pushed out rejected @ pca TN
E	968884	Y	left side damaged wall pushed in & stuff Board
OOS. E	6484	Y	the rail down both sides craked
E	244	Y	Reefer OK
E	30672	Y	Reefer OK
E	989701	Y	SCP. OK
E	8943	Y	Bad floor
L	968873	N	OK Ready
L	2934	N	OK Ready
L	6427	N	Behind truck 385 - OK Ready
L	6442	N	OK Ready
L	6425	N	OK Ready
L	2956	N	Behind truck 6006 - OK Ready
L	8581	N	OK Ready
L	562820	N	OK Ready
L	2685	N	OK Ready behind truck 421
L	8955	N	OK Ready
L	6423	N	OK Ready
L	3183	N	OK Ready
L	8590	N	OK Ready
E	3179	Y	Annual
E	5623036	N	OK Ready
E	968891	N	OK Ready
E	441525	N	OK Ready