10-6-26

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	check wheel bearings
E	44410	Y	brakes drums, wheel bearings
E	8935	Y	wall pushed out.
E	8939	Y	needs plated behind rail.
E	8951	Y	side wall pushed out rejected at PCA TN.
E	968884	Y	left side damged was hit scuffboard pushed in
E	6484	Y	rail down both side cracked.
E	8943	Y	floor needs fixing cracked.
E	244	Y	reefer oh
E	30672	Y	reefer oh
E	985701	Y	scp oh.
E	9581	Y	rail work.
L	6449	n	Ready
L	8949	n	behind TR 373
L	8962	n	behind TR 421
L	3183	n	Ready
E	989635	n	behind TR 103
L	44635	n	behind TR 296