10-14-26

| | E OR L | TRAILER # | LOCK | COMMENTS |
|---|---|---|---|---|
| | E | 44413 | Y | got one fixed like 3 more, wheel bearings |
| | E | 44410 | Y | brakes, drums, wheel bearings |
| | E | 8935 | Y | wall pushed out. |
| | E | 8939 | Y | rail needs plated behind rail. |
| | E | 8951 | Y | left side rail damaged, rail, scuffboard, wall. |
| OOS | E | 6484 | Y | rail check down both sides, noise cover bent. |
| | E | 8943 | Y | new plate by doors, el beam in front, scuffboard. |
| * | E | 8581 | Y | rail work., el beams, scuffboard. |
| * | E | 968874 | Y | scuffboard, |
| * | E | 968884 | Y | was hit skirt damage, scuffboard, |
| OOS | E | 989229 | Y | eddie trl has about 7 I beams, broke, in the middle |
| | E | 244 | Y | reefer ok |
| | E | 30672 | Y | reefer ok |
| | E | 989701 | Y | scp ok. |
| - * | L | 8587 | Y | check tires |
| * | L | 6464 | Y | Hub leaking, 3 I-beams broke. |
| | L | 3180 | n | behind TR 397. |
| | L | 968894 | n | Ready. |
| * | L | 2877 | Y | Annual |
| | L | 8929 | n | Ready |
| | L | 2947 | n | Ready |
| | E | 44680 | n | Ready. |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |