10-21-26

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7+8 I Beams broke, middle by tandems,
OOS	E	6484	Y	rail cracked down both sides, nose corner bent,
	E	44413	Y	got one done, 3 more wheel bearings.
	E	44410	Y	drums, brakes, wheel bearings,
	E	8935	Y	wall pushed out.
	E	8939	Y	rail needs, plated, behind rail,
	E	8951	Y	left rail damaged, scuff board, wall.
	E	8943	Y	new plate by doors, beams front, scuffboard.
	E	8581	Y	rail cracked, needs welding, scuff board,
	E	968884	Y	skirt hit damaged, scuff board.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scp ok.
-	E	989852	Y	ready for Eddie
*	E	8966	Y	Annual check Air Intl.
	L	8931	n	Ready behind TR 421.
	L	6437	n	behind TR 371
	L	6448	n	Ready
	L	6427	n	Ready
	L	2877	n	Ready
	E	562403	n	Ready