10-23-26

	E OR L	TRAILER #	LOCK	COMMENTS
OS	E	989229	Y	7 & 8 il beams broke, middle by tandems
OOS	E	6484	Y	rail cracked, down both sides, raise bent all up.
OOS	E	968884	Y	beam hit cracked rail, scuffboard, broke rail.
	E	968874	Y	tires, mud flap bracket.
	E	44413	Y	got one done, 3 more to go wheel bearings
	E	44410	Y	drums, brakes, wheel bearings.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged scuffboard, wall
	E	8943	Y	il beams in front left side scuffboard.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok.
	E	989701	Y	DCP ok.
*	E	8956	Y	scuff board.
*	E	989778	Y	flat tires LRI LRO.
	L	6428	n	Ready
*	L	8590	Y	W/P
	L	967876	n	behind TR 371
3 *	L	8586	Y	W/P. ABS light.
2 *	E	85930	Y	W/P door rod.
*	L	2946	Y	Bracket on RR brake chamber.
	E	5624036	n	Ready