10-24-24

	E OR L	TRAILER #	LOCK	COMMENTS
OS	E	989229	Y	7 & 8 I beams broke, under tel in back over tand
OS	E	6484	Y	rail cracked, door both sides noise bent all up.
OS	E	968884	Y	beam hit cracked rail, scuffboard, inside wall.
	E	968874	Y	tires, mudflap bracket.
	E	44410	Y	drums, brakes, wheel bearings
	E	44413	Y	one bearing done 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged, scuffboard, wall.
	E	8943	Y	I beam in front left side, scuffboard.
	E	8956	Y	scuffboard.
	E	989778	Y	LRT-2RD tire,
*	E	85930	Y	door rod.
	E	244	Y	Reefer ok
	E	30672	Y	Reefer ok
	E	989701	Y	scp ok
*	L	968878	Y	ABS light.
	L	8590	n	Ready
	L	8581	n	Ready
*	L	6428	Y	Annual.
	L	8587	n	Ready
*	L	2869	Y	Annual
	L	6449	n	Ready
	L	3179	n	Ready
*	L	8932	Y	mudflap.
*	L	6437	Y	Annual
	L	3181	N	Ready
	E	3183	Y	
*	L	2947	Y	Annual