10-26-24

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 & 8 I beams broke under trl by tandems
OOS	E	6484	Y	rail cracked, down both sides, noise bent all up
OOS	E	968884	Y	beam hit cracked rail, scuffboad, inside wall.
	E	968874	Y	tires, mudflap, bracket,
	E	44410	Y	drums, brakes, wheel bearings
	E	44413	Y	one bearing done, 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged, scuffboard wall.
	E	8943	Y	I beam in front left side scuffboard.
	E	8956	Y	scuffboard.
	E	989778	Y	LRI & LRO tie
	E	85930	Y	door rod.
*	E	3183	Y	Tie check, Annual.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scrap ok.
	L	6437	n	Ready
	L	8590	n	Ready
*	L	3175	Y	Annual
	L	3177	n	Ready
*	L	8589	Y	Annual.
	L	6449	n	Ready
	L	3179	n	Ready
	L	968878	n	Ready
	L	3181	n	Ready
	L	2947	n	Ready