10-27-20

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 or 8 I beams broke under trl by tandons
OOS	E	6484	Y	rail cracked down both sides noise bent allway up
OOS	E	968884	Y	been hit cracked rail, scuffboard, inside wall.
	E	968874	Y	tires, mudflaps, bracket,
	E	44410	Y	drums, brakes, wheel bearings,
	E	44413	Y	one bearing done 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged, scuffboard & wall.
	E	8943	Y	I bean in front left side, scuffboard.
	E	8956	Y	scuffboard.
	E	85930	Y	door hod.
	E	3183	Y	tires, LRI leaking, RFO tire to short.
	E	244	Y	reefer ok.
	E	30672	Y	reefer ok
	E	989701	Y	scp, OK
	E	989778	n	Ready for eddie.
	L	8586	n	Ready
	L	5321349	n	Ready
	L	3179	n	Ready
	L	968878	n	Ready
	L	8589	n	Ready
*	L	6442	Y	behind TR 371 Annual
	L	3175	n	Ready
	L	6449	n	Ready