10-28-26

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 or 8 I beams broke under tbl by tandems
OOS	E	6484	Y	rail cracked down both sides noise vent allow up
OOS	E	968884	Y	bear slit cracked rail, scuffboard, inside wall.
S*	E	968874	Y	tires, mudflaps, bracket,
	E	44410	Y	drums, brakes, wheel bearings,
	E	44413	Y	one bearing done 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged, scuffboard & wall.
	E	8943	Y	1 bear in front left side, scuffboard.
1*	E	8956	Y	scuffboard.
	E	244	Y	Keep ok
	E	30672	Y	Keep ok

	E OR L	TRAILER #	LOCK	COMMENTS
	E	989701	Y	sep ok
	E	989778	Y	ready for eddie.
	L	5321349	n	Ready
1*	L	5624262	Y	behind TR 371 LFT TIRE FLAT
	L	3174	n	Ready behind TR 421.
	L	2935	n	Ready
	L	968878	n	Ready
	L	6448	n	behind TR 528
	L	2940	n	Ready
	L	3175	n	Ready
2*	E	3183	Y	get to get a tire off
3*	E	44419	Y	Annual.