10-29-24

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989 229	Y	7-8 I beams broke under tail
OOS	E	6484	Y	rail cracked down both sides nose cone bent
OOS	E	968884	Y	beam hit cracked rail scuffboard, inside wall.
	E	44410	Y	drums, brakes, wheel bearings
	E	44413	Y	one bearing done, 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail needed plated behind rail
	E	8951	Y	left rail damaged, scuffboard, + wall.
	E	8943	Y	I beam front left side, scuffboard.
	E	8956	Y	scuffboard.
	E	244	Y	needs ok
	E	30672	Y	needs ok
	E	989701	Y	needs ok.
	E	989778	Y	ready for eddie
	L	8962	n	Ready
	L	532349	n	Ready
	L	968976	n	behind TR 421
	L	2939	n	Ready
	L	968978	n	Ready
	L	8932	n	behind TR 371
	E	3783	n	Ready
	E	44419	n	Ready
	E	968974	n	Ready