11-3-26

	E OR L	TRAILER #	LOCK	COMMENTS
005	E	989229	Y	7 & 8 I beams broke under trl (tandems)
005	E	6484	Y	rail cracked, down both sides, cover bent all the way up
005	E	963884	Y	beam hit cracked rail, scuffboard, inside wall.
	E	44410	Y	drums brakes, wheel bearings.
	E	44413	Y	one bearing done, 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged. scuffboard, wall.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	985701	Y	dcp ok.
?!	L	8581	n	Ready
?!	L	44524	n	wheel bearing insp, scuffboard insp
	L	2874	n	behind TR 356
	L	6435	n	Ready
	L	6438	n	Ready
	L	2881	n	behind TR 421
	L	8960	n	Ready
*	E	8930	Y	Annual, scuffboard