11-9-24

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 to 8 I beams broke under tub.
OOS	E	6484	Y	rail cracked both sides, corner bent all the way up.
OOS	E	968884	Y	been hit cracked rail, scuff board, inside wall.
	E	44410	Y	drums, brakes, wheel bearings
	E	8935	Y	wall pushed out right side
	E	9951	Y	left rail damaged, scuff board, wall.
	E	8939	Y	rail need plated down the right side.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scp ok.
	E	2881	Y	roof low. Done lady unlock 2881 and took out
	E	990044	Y	ready for eddie.
	L	8929	N	Ready
*	L	968883	Y	door hinge, seal. gone fixed
-	L	968874	n	ready
	L	3174	n	Ready
	L	2956		behind TR 515
	L	968867	n	ready
	L	2874	n	Ready
	L	44286	n	needs to come back ASAP, when empty.
*	L	968887	Y	Annual.
	E	6423	n	Ready
	E	5323589	Y	Annual.