11-10-26

	E OR L	TRAILER #	LOCK	COMMENTS
005	OE	989 229	Y	7 to 8 I beams broke under trl.
005	E	6484	Y	rail cracked both sides, corner bent all the way up.
005	E	968484	Y	brew hit cracked rail, scuffboard, inside wall.
	E	94410	Y	drums, brakes, wheel bearings,
	E	8935	Y	wall pushed out right side.
	E	8951	Y	left rail damaged, scuffboard, wall
	E	8939	Y	rail need plated down right side.
	E	990044	Y	ready for oddie.
	E	989701	Y	sep ok
	E	244	Y	reefer ok
	E	30072	Y	reefer ok.
	E	5323730	Y	brew hit on side
*	L	968883	Y	Annual, mudflaps.
	L	8928	n	ok.
*	L	968880	Y	door seal.
	L	44286	n	needs to come load only for wheel bearing insp.
	L	6458	n	behind TR 421
	L	2948	n	Ok.
	E	6488	n	ok.