11-11-26

	E OR L	TRAILER #	LOCK	COMMENTS
005	E	989229	Y	7 to 8 d beams are broke under tub,
005	E	6484	Y	rail cracked both sides, cover is bent all the way.
005	E	968884	Y	Jeep hit cracked rail scuffboard, inside wall.
	E	44410	Y	drums brakes, wheel bearings,
	E	44286	Y	wheel bearing insp.
	E	8935	Y	wall pushed out right side,
	E	8951	Y	left rail damaged, scuffboard.
	E	8939	Y	rail needed plated down both sides,
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989707	Y	scp ok
	E	990044	Y	ready for eddie,
	E	968867	Y	Annual
	L	8595	n	behind TR 421
	L	8587	n	behind TR 373
	L	8934	n	Ready
	L	6436	n	behind TR 104
	L	6428	n	Ready
	L	2948	n	Ready
*	E	44524	Y	Annual, wheel bearing, brakes wheel seals.
*	E	2882	Y	get new tires