11-12-25

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 to 8 I beams broke under trl
OOS	E	6484	Y	rail cracked, both sides, corner bent all the way up.
OOS	E	968884	Y	beam hit cracked rail, scuffboard, inside wall.
OOS	E	44410	Y	drums, brakes, wheel bearing.
	E	44286	Y	wheel bearing insp.
	E	8935	Y	wall pushed out right side
	E	8951	Y	left rail damaged, scuffboard.
	E	8939	Y	rail need plated down both sides
	E	44524	Y	wheel bearing insp.
	E	990044	Y	ready for eddie.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	Dep Ok
*	L	8938	Y	Annual
	C	2882	n	Ready
	L	5323755	n	Ready
	L	8934	n	Ready
	C	968874		behind TR 421
*	L	8945	Y	multiple u/p in computer
	C	2948	n	Ready
	E	968867	n	Ready