11-13-26

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 to 8 I beams broke under trl
OOS	E	6484	Y	rail cracked, both sides, corner bent all the way up.
OOS	E	968884	Y	bear hit cracked rail, scuffboard, inside wall.
OOS	E	44410	Y	drums, brakes, wheel bearing.
	E	44286	Y	wheel bearing insp.
	E	8935	Y	wall pushed out right side
	E	8951	Y	left rail damaged, scuffboard.
	E	8939	Y	rail need plated down both sides
	E	445241	Y	wheel bearing insp
	E	990044	Y	ready for eddie.

	E OR L	TRAILER #	LOCK	COMMENTS
	E	244	Y	reefer ok
	E	30672	Y	reefer ok.
	E	989701	Y	scp ok.
*	L	2875	*	Annual.
	L	8945	N	Ready
	L	8586	N	Ready
	L	968893	Y	Annual.
	L	5323755	N	Ready
	L	2938	N	Rehid TR 2121
	L	2948	N	Ready
	E	968890	Y	scuffboards
	E	2952	N	Ready
	E	6445	N	Ready