11-14-20

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 to 8 I beams broke under trawl
OOS	E	6484	Y	rail Cracked, both sides, corners bent all the way up
OOS	E	968884	Y	trawl hit cracked rail, scuffboard, inside wall
OOS	E	44410	Y	drums, brakes, Wheel bearing
	E	44286	Y	Wheel bearing insp.
	E	8935	Y	wall pushed out right side
	E	8951	Y	left raid damaged, scuffboard
	E	8939	Y	raid need plated down both sides
	E	44524	Y	wheel bearing insp
	E	990044	Y	ready for eddie
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	Scp ok
	E	8588	Y	Door Rode
	E	6488	Y	Wall Pushed out from floor of trailer can put load between them
	L	8945	N	Ready
	L	2874	N	Ready
	L	8949	N	Ready
	L	2883	Y	Annual
	L	8580	N	Ready
	L	968893	N	Ready
	L	8947	N	Ready, on a workpending Driver said it was hit by another company w/ forklift
	L	2876	N	Ready
	L	2948	N	Ready
	E	968890	Y	scuffboard
	E	8966	N	Ready
	E	8595	Y	RRO Tire
	E	6458	Y	scuffboard