11-29-21.

| | E OR L | TRAILER # | LOCK | COMMENTS |
|---|---|---|---|---|
| OOS | E | 989229 | Y | 7+8 d beams broke under trl. |
| OOS | E | 6484 | Y | rail cracked both sides, corner bent all the way. |
| OOS | E | 968884 | Y | beer hit cracked, rail, scuffboard, inside wall. |
| | E | 44410 | Y | drums, brakes, wheel bearings insp |
| | E | 44286 | Y | wheel bearing insp. |
| | E | 8935 | Y | wall pushed out right side. |
| | E | 8951 | Y | left rail damaged, scuffboard. |
| | E | 8939 | Y | rail need plated down both sides, |
| | E | 44524 | Y | wheel bearing insp; |
| 3 * | E | 8588 | Y | door rod and metal pulled out. |
| | E | 6488 | Y | wall pushed out from the rail of trl. |
| 2 * | E | 6458 | Y | scuffboard. |
| | E | 244 | Y | reefer ok |
| | E | 30672 | Y | reefer ok |
| | E | 989701 | Y | scp ok. |
| | E | 990044 | Y | ready for eddie. |
| | ~~E~~ | ~~6454~~ | ~~Y~~ | |
| 1 * | E | 8960 | Y | right side scuffboard |
| | L | 8580 | N | Ready |
| | L | 6438 | | behind TR421 |
| | L | 8945 | N | Ready |
| | L | 248 | N | Ready |
| | E | 968890 | N | Ready |
| 1 * | E | 8937 | Y | top left hinge, molding & skirt missing, tag light |