11-28-21

	E OR L	TRAILER #	LOCK	COMMENTS
005	E	989229	Y	7+8 I beams broke under trl.
005	E	6484	Y	rail cracked both sides, corner bent all the way
005	E	968884	Y	bear hit cracked rail, scuffboard, inside wall,
	E	44410	Y	drums, brakes, wheel bearings insp
	E	44286	Y	wheel bearing insp.
	E	8935	Y	wall pushed out right side,
	E	8951	Y	left rail damaged, scuffboard.
	E	8939	Y	rail need plated down both sides,
	E	44524	Y	wheel bearing insp.
	E	6488	Y	wall pushed out from rail of trl.
3*	E	8937	Y	Top ~~light~~ ring, molding on skirt tag light.

	E OR L	TRAILER #	LOCK	COMMENTS
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	DCP ok
	E	990044	Y	ready for eddie.
2*	E	8945	Y	Scuffboard,
1.*	L	968879	Y	ABS light, dolly legs,
	L	2945	n	behind trk 609
	L	8580	n	Ready
	L	8947	n	behind TR 421
	L	2948	n	Ready
	E	968880	n	behind TR 296
	E	8960	n	Ready
	E	8588	n	Ready
	E	6458	n	Ready