11-20-24

	E OR L	TRAILER #	LOCK	COMMENTS
005	E	989229	Y	7 & 8 d beams broke under trl.
005	E	6484	Y	rail cracked both sides, corner bent all the way.
005	E	968884	Y	bow bit cracked, rail, scuffboard, inside wall.
	E	44410	Y	doors, brakes, wheel bearings insp
	E	44286	Y	wheel bearing insp.
	E	8935	Y	wall pushed out right side.
	E	8951	Y	left rail damaged, scuffboard.
	E	8939	Y	rail need plated down both sides.
	E	44524	Y	wheel bearing insp.
	E	6488	Y	wall pushed out from rail of trl.
	E	8945	Y	scuffboard.
	E	44180	Y	back corner on left needs fixed rail broke.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok.
	E	989701	Y	scp ok.
	E	990044	Y	ready for eddie.
	L	8597	N	Ready
	L	5323789	N	Ready
*	L	968878	Y	load moved, spring broke.
	L	968879	N	Ready
*	L	5624269	Y	Annual
	L	2827	N	Ready
	L	6434	N	behind TR 421
	L	6450	N	Ready
	E	8937	N	Ready
*	E	8933	Y	RR center marker light out.