

OR L	Trailer #	LOCK	Comments	9-18-24
E	44413	Y	check bearings, ABS cable.	
E	6428	Y	left rail was hit side rail creased	
E	968884	Y	trl was hit in rail damaged rails wall.	
E	8935	Y	wall pushed out both sides	
E	44410	Y	brakes, drums, wheel bearings,	
E	8939	Y	needs to be plated behind rail.	
E	8951	Y	side wall pushed out rejected PCATN.	
E	8933	Y	check out, trl.	
E	844	Y	reefer ok	
E	30672	Y	reefer ok	
E	989701	Y	scpt ok.	
E	968891	Y	need a seal on door.	
L	8931	N	Ready	
L	968867	N	Ready	
L	8952	Y	Annual	
L	2956	N	Ready	
L	968887	N	Ready	
E	8941	Y	behind TR 103 need Annual.	
L	8961	N	Ready	
L	6472	N	Ready behind TR 421.	
L	8588	N	Ready	
E	6432	N	ok.	
E	8590	Y	Roof Bow. Annual	

V235-EX225L266X001