

9-23-26

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	check wheel bearings
E	6428	Y	left rail was hit side wall creaked.
E	968884	Y	til was hit in rail damaged rail & wall.
E	8935	Y	wall pushed out both sides
E	44410	Y	brakes, drums, wheel bearings
E	8939	Y	needs plated behind the rail.
E	8951	Y	side wall pushed out rejected at PCA Tr.
E	989674	Y	ready for eddie,
E	968876	Y	scuff board,
E	968879	Y	scuff board
E	249	Y	reep ok
E	30672	Y	reep ok
E	989701	Y	reep ok.
E	6445	Y	brakes,
E	3175	Y	7 beams 4 needs welding.
L	3180	Y	brakes
L	968871	n	body
L	8963	n	body
L	968887	n	body
L	968865	n	behind TR 296
L	3176	n	body
E	6429	Y	Annual.