

9-11-26

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	ABS cable, check bearings
E	6428	Y	Left rail was hit and cracked rail.
E	968884	Y	the bar hit in rail & side panel.
E	8935	Y	wall pushed out both sides.
E	44410	Y	bushes, drums, wheel bearing
E	8939	Y	needs to be plated behind rail.
E	244	Y	refr ok
E	30672	Y	refr ok
E	989701	Y	refr ok.
E	5323789	Y	want slide tandoms
E	6443	Y	needs bushes w/ front axle.
E	6439	Y	Annual.
W/P *	L	8931	n right landing gear bound up check by. * (K190) 4/1
*	L	6434	Y Annual. *
	L	2884	n behind TR 510 good used tires
	L	2944	n ready good used tires
/	E	5624269	N Ready
*	L	968828	n ready needs to look at again w/p. (K190) 4/1
	L	3178	n ready
*	L	6441	Y behind TR 371 Annual.
	L	5621820	n Ready
	L	2885	n Ready
/	E	4587	n Ready
A	E	2874	n behind TR 524 good used tires on it too
	E	968897	n Ready.