

9-24-26

E OR L	TRAILER #	LOCK	COMMENTS
E	44413	Y	check wheel bearings
E	6428	Y	left rail was hit side wall cracked,
E	968884	Y	til was hit in rail, danged rail & wall.
E	8935	Y	wall pushed out both sides
E	44410	Y	brakes, drums, wheel bearings
E	8939	Y	needs plated behind rail
E	8951	Y	side wall pushed out, rejected at KA TN.
E	968876	Y	scuff board.
E	968879	Y	scuff board.
E	989674	Y	ready for eddie,
E	244	Y	reefer ok
E	30672	Y	reefer ok
E	989701	Y	scp ok.
L	3180	n	Ready
L	968867	n	Ready
L	968871	n	Ready
* L	2876	* n	light tail w/p
L	5624025	n	behind TR 523
L	968887	n	Ready
L	8965	n	behind TR 296
L	8962	n	behind TR 421
* L	8963	* n	ready w/p lights, dolly log.
E	6429	n	Ready
E	3175	n	Ready
E	6451	n	Ready
E	2870	n	Ready
E	968870	Y	Ready