10-7-26

	E OR L	TRAILER #	LOCK	COMMENTS
	E	44413	Y	check wheel bearings
	E	44410	Y	brakes, drums, wheel bearings
	E	8935	Y	wall pushed out.
	E	8939	Y	needs plated behind rail
	E	8951	Y	side wall pushed out rejected at PCA TN.
	E	968884	Y	left side bent hit damaged rail & scuffboard & mar.
	E	6484	Y	rail cracked down both sides
	E	8943	Y	floor scuffboard, damage need plate by the door in p
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	reefer ok
	E	8581	Y	rail work.
*	L	8932	Y	Annual.
	L	3175	N	tires are looking rough on left side.
*	L	2948	Y	Annual
	L	6448	N	Ready
	L	968865	N	behind TR 421
	L	5323789	N	behind TR 291
	L	3183	N	Ready