10-16-26

	E OR L	TRAILER #	LOCK	COMMENTS
	E	44413	Y	check wheel bearings
	E	44410	Y	brakes, drums, wheel bearings
	E	8935	Y	wall pushed out.
	E	8939	Y	needs plated behind rail
	E	8951	Y	left side rail damaged rail, scuffboard, + wall.
005	E	6484	Y	rail checked down both sides
	E	8943	Y	need new plate by doors, scuffboard.
	E	8581	Y	rail work.
	E	968874	Y	scuffboard.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	ref ok.
	E	6478	Y	I Beams broke, floor. air tank.
	L	2956	n	Ready
	L	6472	n	Ready
	L	2955	n	Ready
	L	8582	n	Ready
	L	6438	n	Ready
	L	968894	n	Ready
*	L	2944	Y	air leak.
*	L	2885	n	going to need new tires pretty quick
	L	8596	n	Ready
	L	5624256	Y	check mudflap + rail
*	E	44880	Y	hole front left corner.
	E	6445	n	Ready
	E	8929	n	Ready
	E	6427	n	Ready