10-13-26

	E OR L	TRAILER #	LOCK	COMMENTS
	E	44413	Y	check wheel bearings
	E	44410	Y	brakes, drums, wheel bearings
	E	8935	Y	wall pushed out.
	E	8939	Y	needs plated behind rail.
	E	8951	Y	left side rail damaged, rail, scuffboard, wall.
OS	E	6484	Y	rail is cracked down both side, noise cover bent.
	E	8943	Y	new plate by doors, I beams in front, scuffboard.
	E	8581	Y	rail wak.
	E	968874	Y	scuffboard,
OS	E	979229	Y	eddie trl has about 7 beams broke in the middle
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scg ok.
*	E	8944	Y	abs, light air leak, rust a part of trl.
*	E	968884	Y	was hit skirt damage. scuffrail.
	L	2871	n	behind TR. 511
	L	968894	n	Ready
	L	8945	n	behind TR 373
X	L	3181	n	behind TR 103
	L	8562	n	behind TR 421
*	L	8528	n	behind TR 371 Annual
	E	44680	n	Ready
	E	6478	n	Ready.