10-15-26

	E OR L	TRAILER #	LOCK	COMMENTS
	E	44413	Y	got one fixed like 3 more wheel bearings
	E	44410	Y	brakes, drums, wheel bearings
	E	8935	Y	wall pushed out.
	E	8939	Y	rail needs plated behind rail.
	E	8951	Y	left rail damaged, rail, scuffboard, wall.
OOS	E	6484	Y	rail cracked down both sides, noise cone bent
	E	8943	Y	needs new plate by doors, I beams in front, scuffb
	E	8581	Y	fw cracks in rail need welded, scuffboard.
OOS	E	989239	Y	eddie tal has 7 I beams, broke in middle
	E	968884	Y	was hit skirt damage, scuffboard.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scp ok.
*	L	2950	N	~~Ready~~ needs to come back to shop for work
	L	968887	N	Ready
	L	968894	N	Ready
	L	6429	N	Ready
	L	6437	N	behind TR 371
	L	2877	N	Ready