10-16-26

E OR L	TRAILER #	LOCK	COMMENTS
E	444[illegible]3	Y	got one fixed like 3 more wheel bearings
E	44418	Y	brakes, drums, wheel bearings
E	8935	Y	wall pushed out.
E	8939	Y	rail needs plated behind rail.
E	8951	Y	left rail damaged rail scuffboard, wall.
OOS E	6484	Y	rail creched down both sides noise conv. bent.
E	8943	Y	needs new plate by doors, il leans, in front scuffboa
E	8581	Y	few cracks in rail need welding. scuffboard.
OOS E	989229	Y	eddie tel has 7 broke il leans in the middle.
E	968484	Y	was hit skirt damaged, scuffboard.
E	5624262	Y	hole in roof.
E	244	Y	reefer ok
E	30072	Y	reefer ok
E	989701	Y	reefer ok.
L	6472	Y	wont slide,
L	2955	Y	check tires
L	85930	Y	check brakes w/p.
L	8927	N	Ready
L	2947	Y	RRO tire has nail
L	8590	Y	Annual.
L	6448	Y	Annual.
L	964887	N	Ready
L	6450	Y	behind TR 371 Annual.
L	2877	N	Ready