10-20-26

	E OR L	TRAILER #	LOCK	COMMENTS
	E	44413	Y	got one bearing like 3 more, bearings
	E	44410	Y	drums, brakes, wheel bearing
	E	8935	Y	wall pushed out,
	E	8939	Y	rail needs plated behind rail.
	E	8951	Y	left rail damaged, rail scuffboard, wall.
005	E	6484	Y	rail cracked down both sides noise cover bent all.
	E	8943	Y	needs new plate by doors, I beams in front, scuffboard
	E	8581	Y	cracked in rail needs welding, scuffboard.
005	E	989229	Y	tail has 7 brake I beams in middle, by tandems
	E	968884	Y	hit skirt damaged, scuffboard.
	E	5624262	Y	hole in roof,
	E	989717	Y	Annual,
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	scp ok.
	E	968874	Y	the kick plate needs fixed, scuffboard.
	L	5323755	Y	needs tire LRT
	L	2885	n	Ready
	L	2955	n	Ready
	L	6448	n	Ready
	L	8962	n	behind CR 371
	L	2877	n	Ready
	E	5624036	Y	bent & hole in corner