10-30-26

	E OR L	TRAILER #	LOCK	COMMENTS
005	E	989229	Y	7 or 8 I beams broke under trl.
005	E	6484	Y	rail craked, down both sides, corner bent all the way
005	E	988884	Y	beer hit cracked, rail, scuffboard, inside wall.
	E	44410	Y	drums, brakes, wheel bearings
	E	44413	Y	one bearing done, 3 more to go.
	E	8935	Y	wall pushed out.
	E	8939	Y	rail need plated behind rail.
	E	8951	Y	left rail damaged, scuffboard, + wall.
	E	244	Y	reefer ok
	E	30672	Y	reefer ok
	E	989701	Y	DCP ok.
	E	98778	Y	ready for eddie.
/	L	8581	n	Ready
*	L	2882	n	TRL got 7 good tires we can use.
	L	2868	n	get all new tires on it
	L	8963	n	Ready
*	L	8962	W/P.	Plate bent at rear of trl
	L	44286	Y	Annual.
*	L	2941	Y	RRI Tire Flat. TR 421.
	L	6438	n	Ready
	L	2939	n	Ready
*	L	6485	Y	Annual.
*	L	2878	L	behind TR 371 All tires need to come off
	E	8943	n	Ready
	E	8956	n	Ready
*	E	8930	Y	Annual + scuffboard.