E OR L	TRAILER #	LOCK	COMMENTS
OOS E	989229	Y	7 or 8 ~~Rotts~~ I beams broke under trailer
OOS E	6484	Y	rail Craked, down both sides, corner bent all the way
OOS E	968884	Y	beam hit craked, rail scuffboards, inside wall
E	44410	Y	drums, brakes, wheel bearings
E	44413	Y	one bearing done 3 more to go
E	8935	Y	wall pushed out
E	8939	Y	rail need plated behind rail
E	89~~3~~1	Y	left rail damged, scuffboard, & wall
E	244	Y	reefer ok
E	30672	Y	reefer ok
E	989701	Y	SCP OK
E	989778	Y	~~Red~~ ready for Eddie
L	8581	N	Ready
L	968876	N	Ready
L	2882	N	Ready
L	8597	Y	Annual
L	2868	N	It Ready put new tires on it
L	8963	N	Ready
L	6429	Y	Air leak
L	8962	W/P	Plate bent at rear of trailer
L	2940	Y	Annual
L	968874		Ready
L	6438	N	Ready
L	2939	N	Ready
L	6472	Y	leaking Air at plug in air tank
L	2442	N	Ready
L	8960	N	Ready
L	44286	N	Ready
L	8595	Y	Annual
E	2486	N	Ready
E	8930	Y	Annual / scuff board