11-4-26

	E OR L	TRAILER #	LOCK	COMMENTS
005	E	989229	Y	7&8 I beams broke, under trl, tandems
005	E	6484	Y	rail cracked, down both sides, cover bent all the way
005	E	968884	Y	rear hit cracked rail, scuffboard inside wall.
	E	44410	Y	drums, brakes, wheel bearings,
	E	44413	Y	ae bearing left
	E	8935	Y	wall pushed out.
	E	8951	Y	left rail damaged, scuffboard, wall.
	E	244	Y	reefer ok.
	E	30672	Y	reefer ok
	E	98701	Y	scap ok needs a Annual when not busy.
X	E	8947	Y	Sand shoe rusted out.
	L	5323729	n	
	L	6438	n	Ready
	L	8933	n	behind TR 371
	L	8586	n	behind TR 421
	L	2887	n	behind TR 104
	E	8930	n	Ready