11-6-24

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 + 8 I beams broke, under trl,
OOS	E	6484	Y	rail cracked down both sides cover bent all the w
OOS	E	968884	Y	bear hit cracked, rail, scuffboard, inside wall.
	E	44410	Y	drums, brakes, wheel bearings
	E	8935	Y	wall pushed out.
	E	8951	Y	left rail damaged, scuffboard, wall.
	E	8947	Y	ABS light.
	E	244	Y	reefer ok.
	E	30677	Y	reefer ok
	E	989701	Y	scp ok.
	E	990044	Y	ready for eddie.
*	E	6440	Y	scuffboard, mudflap
	L	8932	n	Ready
*	L	6458	n	got scuffboard damage needs to come back empty to g
	L	5623036	n	Ready
	L	8965	n	Ready
	L	3182	n	Ready
	L	2485	n	behind TR 371
	L	968874	n	behind TR 421
	E	44413	n	Ready