11-17-26

	E OR L	TRAILER #	LOCK	COMMENTS
OOS	E	989229	Y	7 & 8 I beams broke under trl.
OOS	E	6484	Y	rail cracked, both sides, corner bent all the way up.
OOS	E	968884	Y	been hit cracked rail, scuffboard, inside wall.
	E	44460	Y	drums brakes, wheel bearings
	E	44286	Y	wheel bearing insp
	E	8935	Y	wall pushed out, right side.
	E	8951	Y	left rail damaged, scuffboard.
	E	8939	Y	rail need plated down both sides.
	E	44524	Y	wheel bearing insp.
	E	8588	Y	door rod and metal pulled out.
	E	6488	Y	wall pushed out from floor of trl.
	E	989842	Y	
	E	244	Y	roof rot.
	E	30172	Y	roof rot
	E	989701	Y	scp rot
	L	2868	N	right hand corner., cracked, in 2 different,
	L	8580	N	door, left side door handel, mast latch
	L	968874	N	behind TR 421
	L	2948	N	dirty
	E	968890	Y	scuffboard
	E	6458	Y	scuffboard.
	E	990044	Y	ready for eddie