TRUCK #	10-9-26 COMMENTS
360	install Front Pads
375	Drivers side Steps
Moffett	Finish Service
528	NTI Finished
529	NTI Finished
530	NTI Finished
531	NTI Finished
532	NTI
363	Transmission issues
355	Bad Engine
358	check 22
364	Hood Damage & check Drive lines
512	Transmission issues, Spring pin Bushings
513	Foward Diff Leak
370	Ok
373	Ok
103	A Service
104	Mirror & Hood Bushings
421	Exhaust Bracket Broken
520	Ok
394	Ok
360	Bill new Rims
371	Ok
296	Transmission Faults