TRUCK #	10-B-26 COMMENTS
375	passenger side fairing
364	Fan hub
363	Transmission issues
355	Bad Engine
358	check 22
364	Hood Damage
512	Transmission issues & spring pin Bushings
513	Foward Diff leaking
511	Brake Light switch
373	A & B Service
421	A Service
371	Ok
103	A Service
104	Ok
370	Ok
395	Ok
379	Ok
360	Ok
369	check coolant level
387	Ok
296	Transmission Faults